


NCK IOS TOOL

Things you need to do before you start using this tool.

1. Download and install itunes
2. Download and install 3utools
3. Download and install .net framework
4. Down WinRa1n 1.0 from support


How to make Activation of Hello Screen Activation without SN Change




Step 1:

1. Start UMT IOS Tool providing you have EMMC Addon Activation Active.
2. Select Ramdisk (IOS Version) , if your phone IOS 16.6 Please do not try yet.
3. Power on Phone in normal mode and connect usb cable, once you get msg on pc and phone to trust device, please do.
4. Check for Success Log then....

NCK IOS TOOL




5. Select Get Activation (Hello Screen Normal Mode).
6. Press Do Job and wait for log.
7. Upon success press OK.



8. Start WinRaIn Software Put Phone in DFU Mode , Select Check8 Option if not auto selected.


NCK IOS TOOL

- Once Phone is detected Pres Fix Drivers.
- After the Next Button will be highlighted, press Next and follow instruction to put phone in DFU mode and it will auto start process of PWNDFU.
- After Success PWNDFU , (if it fail first-time repeat until done).
- Click on Check Device DFU Mode , Make sure in long it show status of PWNDFU.



- Click on Boot Ramdisk PWNDFU
- Wait until success log as in screenshot above.

NCK IOS TOOL



15. Select Activate Hello-Ramdisk Mode from drop menu of (Bypass Hello).
16. Press Do job and wait for success operation.
17. Wait until phone restarts and enjoy.